



Vertical cracks through the top two pinnacle stones



Concrete fill to the base of the iron cross



Base of the corroded iron rod ended in a pocket 5 courses below the cross. Sample of Crosland Hill sandstone, (grey/ buff ) adjacent to face stonework.



Sample of Crosland Hill sandstone, (grey/ buff ) adjacent to piece of freshly broken existing stone